

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION


PATENT NO. : 7,001,861 B2
APPLICATION NO. : 10/626317
DATED : February 21, 2006
INVENTOR(S) : George Halsey Beall et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<i>No.</i>	<i>Col.</i>	<i>Line</i>	<i>Description</i>
1	10	37	“ $0.33 \times 10^{-10} \text{ m}^2$ ” should be -- $0.33 \times 10^{-12} \text{ m}^2$ --.
2	11	7	“ (.1SrO- ” should be -- (1.1SrO- --.
3	12	3	“ u 0.6965 ” should be -- u=0.6965 --.

Signed and Sealed this
Sixth Day of March, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office